



1500 Brigantine Drive  
Coquitlam, BC, V3K 7C1

Telephone: 604-520-3321  
Facsimile: 604-524-9186  
www.intertek.com

August 1, 2012

Project No. G100400406

Tuff Industries Inc.  
9570 Bottom Wood Lake Road  
Lake Country, BC V4V 1S7

Ph: 250-766-1333  
email: info@tuffindustriesinc.com

**Subject: Findings Letter Report 100400406COQ-003J**


Dear Mr Hughes,

The submitted Tuff Industries Inc. sample, identified as Econodek "Contractor Series 60", has met the following performance criteria:


- All performance requirements of Canadian General Standards Board CAN/CGSB-37.54-95, *Polyvinyl Chloride Roofing and Waterproofing Membrane*, as outlined in Intertek Report No. 100400406COQ-003H
- All performance requirements, with the exception of the elongation properties of ASTM D 4434-11, *Standard Specification for Poly (Vinyl Chloride) Sheet Roofing*, as outlined in Intertek Report No. 100400406COQ-003I

If there are any questions regarding the results contained in this report, or any of the other services offered by Intertek, please do not hesitate to contact the undersigned.

Completed by: Chris Chang, EIT  
Title: Test Engineer

Signature: 

Reviewed by: Baldeep Sandhu, ASCT  
Title: Technologist

Signature: 

This report is for the exclusive use of Intertek's Client and is provided pursuant to the agreement between Intertek and its Client. Intertek's responsibility and liability are limited to the terms and conditions of the agreement. Intertek assumes no liability to any party, other than to the Client in accordance with the agreement, for any loss, expense or damage occasioned by the use of this report. Only the Client is authorized to permit copying or distribution of this report and then only in its entirety. Any use of the Intertek name or one of its marks for the sale or advertisement of the tested material, product or service must first be approved in writing by Intertek. The observations and test results in this report are relevant only the sample tested. This report by itself does not imply that the material, product or service is or has ever been under an Intertek certification program.

